

Title: Method And Apparatus For Improving Noise Immunity For Low Intensity Optical Communication Inventor: Jurgis Astrauskas

Emerson Docket No.: M-7373/ MMB Docket No. 1007-0566


Replacement Sheet 1 of 15





Emerson Docket No.: M-7373/ MMB Docket No. 1007-0566

Replacement Sheet 2 of 15







Fig-4

Title: Method And Apparatus For Improving Noise Immunity For Low Intensity Optical Communication Inventor: Jurgis Astrauskas


Emerson Docket No.: M-7373/ MMB Docket No. 1007-0566

Replacement Sheet 3 of 15



Title: Method And Apparatus For Improving Noise Immunity For Low Intensity Optical Communication Inventor: Jurgis Astrauskas


Emerson Docket No.: M-7373/ MMB Docket No. 1007-0566 Replacement Sheet 4 of 15



Title: Method And Apparatus For Improving Noise Immunity For Low Intensity Optical Communication


Emerson Docket No.: M-7373/ MMB Docket No. 1007-0566

Replacement Sheet 5 of 15



Emerson Docket No.: M-7373/ MMB Docket No. 1007-0566

Replacement Sheet 6 of 15



Emerson Docket No.: M-7373/ MMB Docket No. 1007-0566

Replacement Sheet 7 of 15




FIG 9A




FIG 9B

Emerson Docket No.: M-7373/ MMB Docket No. 1007-0566 Replacement Sheet 8 of 15






FIG 10

Emerson Docket No.: M-7373/ MMB Docket No. 1007-0566 Replacement Sheet 9 of 15




Emerson Docket No.: M-7373/ MMB Docket No. 1007-0566

Replacement Sheet 10 of 15



Emerson Docket No.: M-7373/ MMB Docket No. 1007-0566


Replacement Sheet 11 of 15



Emerson Docket No.: M-7373/ MMB Docket No. 1007-0566 Replacement Sheet 12 of 15

FIG 16A

280










FIG 17

Emerson Docket No.: M-7373/ MMB Docket No. 1007-0566 Replacement Sheet 13 of 15



Emerson Docket No.: M-7373/ MMB Docket No. 1007-0566

Replacement Sheet 14 of 15



Emerson Docket No.: M-7373/ MMB Docket No. 1007-0566

Replacement Sheet 15 of 15

